

Building Dashboard

Vetero	ans' Memoria	al Field F	louse	Silver Street					
Building Data									
Structural Details			HVAC		Condition	Appliances	Type/age		
fear Built	1930		Heating System	Oil fired Hot Water	GOOD	Interior Lighting	T8s		
quare footage	7,200		Air Conditioning	None		Exterior Lighting	LED Flood in parking lot one wall light		
invelope	Masonry section, wood f	rame section for	Hot Water Heater	Indirect from Boiler	GOOD	Vending Machines	None		
Roof	slightly pitched, rolled roofing over wood deck		Ventilation	None		Ice machine	New in 2016		
Vindows	vinyl framed double glazed		Heat Distribution	Two-pipe system					
nsulation	None		Controls	Thermostat and low limit thermostat on time clock					
Building Summary	Contains a heated masonry section and unheated wood-frame storage section. Heated section contains office and locker rooms, also has an uninsulated attic. Only used for afterschool practice and games. Heating system retrofited from steam to hot water in 2007. Winterized annually since 2016. New washing machine and dryer installed in 2018								
Energy Profile - FY2021			Usage Trends ■ Monthly Use ■ Annual Use (12 Month Rolling Sum) An asterisk over a bar indicates building interventions completed in that month. Click on the bar to display						
Energy Usage		more information abo		FY 2016	FY 2020 FY 20	021			
Electric (kWh)	Heat (gallons)	EUI (kBTU/sqft)	8K-				- 30K		

Energy Profile - FY2021						
Energy Usage						
Electric (kWh)	Heat (gallons)	EUI (kBTU/sqft)				
11,599	0	5				
EUI ≤ 35 Meets Zero Energy Goal	EUI = 35-50 Efficient	EUI >50 Priority to Improve				
Annual Energy Cost						
Electric	Heat	Total				
\$2,290	\$0	\$2,290				
Berkshire Gas Rate C	<u>N/A</u>					
Electric Service Rate	<u>G0</u>					
Average Monthly De	2					



Audits/Assessments						
Fiscal Year	Туре	Findings				
2009	Siemens Whole building assessment	Report available upon request				
2014	Clearesult	Report available upon request				
2016	Internal Solar Assessment	Inadequate site for solar				